

Corner originally set as a post in 1820 by John Hendricks with the following witnesses: 26" elm bearing north 88 degrees, thence west 10 links; and a 12" dogwood bearing south 67 degrees, thence east 28 links. (M.C.Atlas p. 9) A survey by D.B.Hasbrook on June 10,1851 indicates a 16" oak bearing north 21.50 degrees, thence west 18 links. (Perry Legal Book p. 24) Corner referenced by Sutton on 5/23/60 and called a stone 6" down. Corner referenced by Fleener on 6/6/69 and called a R.R. spike. Corner referenced by MCS in 1972 and called a R.R.spike. Corner referenced by Wilcoxen on 8/25/75 and called a p.k. Nail. Corner referenced by Wilcoxen on 11/16/87 and called a R.R. spike. Corner referenced by Whiteside on 3/12/96 and called a R.R.spike. Corner referenced by Whiteside on 3/11/02 and called a R.R. spike. Corner excavated on 10/09/03 by Wilcoxen and a R.R. spike was found 7" down. A stone with a cut x was found 16" down. A #205 cast iron Harrison monument was set in position as the corner.

14042007		
REF.	DISTANCE	DESCRIPTION
1.	50.37'	Mag nail w/brass washer SE PwP#147-820 15"up
2.	44.97	Cut 'x' in curb
3.	41.15	cut 'x' in curb
4.	101.71	Cut 'x' SE corner of metal post of sign 36"up
5.	34.25	cut 'x' in curb
6.	112.79	SE corner of Brick columns